

Illinois Commerce Commission**Pipeline Safety****Pipeline Safety Report****Inspection #: 2015-P-00387**

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Exit Meeting Contact: Kevin Glaspy	Total Man Days: 3
Pipeline Safety Representative(s): Donald Hankins	
Company Representative to Receive Report: Michael Fuller	<u>Emailed Date:</u>
Company Representative's Email Address: mfuller2@ameren.com	12/16/2015

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Field Audit	Tuscola	Donald Hankins	Tuscola	0.5	8/4/2015 (Half)	
Design Testing and Construction	Tuscola	Donald Hankins	Tuscola	2.5	8/4/2015 (Half), 8/5/2015, 8/6/2015	Kevin Glaspy

Statement of Activities

On August 4, 5, & 6, 2015, staff conducted a field audit and a construction audit for Ameren Illinois, in Tuscola, Illinois. The audit was conducted to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590.

On August 4, 2015, for a half of a day staff conducted a field audit by inspecting line markers, with the line markers having the proper emergency phone number placed on them, 1-800-755-5000. Staff then inspected regulator Stations, and markings of pipe and fittings, in the warehouse in Tuscola.

On August 4, 2015, Ameren Illinois started installing a new service line in at 101 South Ellen Street in Homer, Illinois. On August 5, 2015, Ameren finished the new service line in Homer, Illinois. The service line was a 1/2 inch plastic service line, and was air tested to 100 psig for at least 10 minutes, with no leaks being found at the time of installation.

On August 6, 2015, Ameren Illinois installed a new service line at 415 East Illinois Street, in Tuscola, Illinois. The service line was a 1/2 inch Driscopex plastic line, and was air tested to 100 psig for at least 10 minutes, with no leaks being found at this time.

Exit Statement**INSPECTION FINDINGS****Design Testing and Construction****Issues(s) Found:**

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

Illinois Commerce Commission
Pipeline Safety
Pipeline Safety Report

Inspection #: 2015-P-00387

[NO NOPVS FOUND]

Standard Inspection - Field Audit

Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]